

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	559	vco and amplifier and lc and feed\$1back	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/13 09:17			0
2	BRS	137	feed\$1back same amplifier same (positive near peak)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/13 09:19			0
3	BRS	0	(vco and amplifier and lc and feed\$1back) and (feed\$1back same amplifier same (positive near peak))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/13 09:19			0
4	BRS	1209	331/117R.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/13 09:20			0
5	BRS	48	(vco and amplifier and lc and feed\$1back) and 331/117R.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/13 09:20			0